

49/001

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan. 1, 1993 To (mo./yr.) Dec. 31, 1993
2. DOGM File Number (Mine No): M / 049 / 001
3. Mine Name: Keigley Quarry
4. Mineral(s) Mined (or permitted to mine): Limestone / Dolomite
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
Part of 1/4, 1/4, Section 15 & 16 Township 9S, Range 1E
Part of 1/4, 1/4, Section 22 & 23 Township 9S, Range 1E
Part of 1/4, 1/4, Section 26 & 27 Township 9S, Range 1E
7. Name of Operator or Company: Geneva Steel
8. Permanent Street Address : P.O. Box 2500
City, State, Zip: Provo, Utah 84603
Phone: 801-227-9000
9. Company Representative (or designated operator):
Name: W. Roy Benson
Title: Division Manager - Mining
Business Address: Box 20-B, RFD #1
City, State, Zip: Santaquin, Utah 84655
Phone: 801-465-2532 / 227-9000
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 205,680

3. How much **additional** acreage was disturbed during the past year? None

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

None

5. How much acreage was reclaimed during the past year? 2.5 acres

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Approx. 1500 yd³ of loamy top soil from the highline canal was gathered and spread on the dump to a depth of approx. 6".

Sub was scarified and ripped to a depth of 1 foot. Seeded with approved mix.

As more top soil is gathered more area will be reclaimed.

7. What is the total disturbed acreage at years end? 401.5 including reseed area.

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Monitor current seeding for success and normal mining will occur.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

W. Roy Benson

Title of Operator:

Div. Manager - Mining

Signature of Operator:

W. Roy Benson

Date:

January 31, 1994